

GOSSEN Battery Adapter

for Ordering No. V204A

Lunasix 3/S

New Non-Mercury Batteries


Please use Silver-Oxide Batteries (2x),

1.55 Volts each:

IEC SR 44 e.g. Varta V 76 PX
Duracell D 357 H

How to insert the new batteries:

- Place adapter pot into the battery chamber
- Insert new batteries
- Close the battery chamber and proceed according to page 7 of the Operating Instructions of your Lunasix 3/S.



GOSSEN Foto- und Lichtmeßtechnik GmbH

Lina-Ammon-Str. 22

90471 Nuremberg, Germany

Phone: +49 911 / 8602-181

Fax: +49 911 / 8602-142

<http://www.gossen-photo.de>

GOSSEN