

## SP-445 Mold line

A few tanks have noticeable parting lines from the mold, (on the inside sealing surface as shown below). The line on the beveled surface (top half) doesn't affect sealing but the line on the bottom surface might, since that is where the O-ring "seats". You can *gently* polish down with 320 or 400 grit wet/dry sandpaper & water. Be careful, it doesn't take much pressure to remove material. Note that it doesn't have to be perfectly smooth to seal well.

